

Where Automation Connects.



PLX51-PBM

PROFIBUS DP Master/Slave to EtherNet/IP™, Modbus TCP/IP®, or Modbus® Serial Gateway

Your Feedback Please

We always want you to feel that you made the right decision to use our products. If you have suggestions, comments, compliments or complaints about our products, documentation, or support, please write or call us.

ProSoft Technology, Inc.

- +1 (661) 716-5100
- +1 (661) 716-5101 (Fax)

www.prosoft-technology.com ps.support@belden.com

PLX51-PBM Release Notes For Public Use.

June 30, 2025

ProSoft Technology®, is a registered copyright of ProSoft Technology, Inc. All other brand or product names are or may be trademarks of, and are used to identify products and services of, their respective owners.

Content Disclaimer

This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither ProSoft Technology nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein. Information in this document including illustrations, specifications and dimensions may contain technical inaccuracies or typographical errors. ProSoft Technology makes no warranty or representation as to its accuracy and assumes no liability for and reserves the right to correct such inaccuracies or errors at any time without notice. If you have any suggestions for improvements or amendments or have found errors in this publication, please notify us.

No part of this document may be reproduced in any form or by any means, electronic or mechanical, including photocopying, without express written permission of ProSoft Technology. All pertinent state, regional, and local safety regulations must be observed when installing and using this product. For reasons of safety and to help ensure compliance with documented system data, only the manufacturer should perform repairs to components. When devices are used for applications with technical safety requirements, the relevant instructions must be followed. Failure to use ProSoft Technology software or approved software with our hardware products may result in injury, harm, or improper operating results. Failure to observe this information can result in injury or equipment damage.

© 2025 ProSoft Technology. All Rights Reserved.

Printed documentation is available for purchase. Contact ProSoft Technology for pricing and availability.

ProSoft Technology, Inc.

Page 2 of 6

Contents

	Your F	eedback Please	2
	Conte	nt Disclaimer	2
1		art Here	Δ
<u> </u>	010	art riolo	
	1.1	About the PLX51-PBM	4
	1.2	Release Enhancements	4
2	Su	6	
	2.1	Contacting Technical Support	6
	2.2	Warranty Information	

1 Start Here

This document highlights the new features, fixes, enhancements and known issues for the PLX51-PBM.

1.1 About the PLX51-PBM

The PLX51-PBM gateway provides connectivity to EtherNet/IP™, Modbus TCP/IP®, or Modbus® Serial networks for PROFIBUS DP networks by operating as either a Master or Slave device on the PROFIBUS DP network.

1.2 Release Enhancements

Release	Release	Description
Version	Date	
1.001.045	17-Jun-2025	New Features Network parameters can now be saved on the SD Card, which will allow a factory default module to also update the network parameters from the SD Card on startup. Updated DP Master Comms to match that of the PXM. PXM had enhancements to better manage when two masters share a DP network, as well as handling noisy DP networks.
		 Fixes & Changes Resolved issue where M580 SE Controller HSBY swap would result in long delay before PLX51-PBM reconnects. Resolved issue where odd number of bytes in the last slot with a SINT datatype (when using Modbus) would overwrite the next device data exchange. Resolved extra byte being copied to Modbus register when odd bytes in mapping. Resolved multiple bytes with odd total number not being copied correctly to PROFIBUS output. Resolved anomaly with SD Card Configuration backup that could cause the module to lock up on startup. Limited DP parameter and configuration size to avoid a buffer overrun with incorrect GSD files.
1.001.042	1-Nov-2022	Minimum firmware revision required to run on hardware with the "HB" designation in the F/W REV product label.
1.001.041	30-Jun-2021	New Features Added support to emulate Legacy Prolinx slave device EtherNet/IP Explicit Messaging feature Added support to allow a PROFIBUS DP Master to upload configuration (PLX51-PBM Slave Mode) Added byte/word swapping at device level Added option to force DP Slave data to 0 during communication loss (PLX51-PBM Master mode) Added support for Modbus Function Codes 5 & 6 Added support for slave devices with PROFIBUS Identity 0.

ProSoft Technology, Inc.

Page 4 of 6

1.001.038	31-Mar-2021	New Features Added Non-SINT Array support Added Modbus Communication Status DP Slaves online during communication failure feature Fixed PROFIBUS Endian format in Modbus modes for INT data types
1.001.035	1-Jul-2020	New Features Added Modbus TCP/IP and RTU functionality Added support for importing legacy PCB files Fixes & Changes Shows major, minor, and build revisions in the target browser & device flash Fixed TCP/ARP window display Data Exchange bits to clear after slave node address is changed during data exchange.
1.001.017	28-Aug-2019	Release

ProSoft Technology, Inc.

Page 5 of 6

2 Support, Service & Warranty

2.1 Contacting Technical Support

ProSoft Technology, Inc. is committed to providing the most efficient and effective support possible. Before calling, please gather the following information to assist in expediting this process:

- 1 Product Version Number
- 2 System architecture
- 3 Network details

If the issue is hardware related, we will also need information regarding:

- 1 Module configuration and associated ladder files, if any
- 2 Module operation and any unusual behavior
- 3 Configuration/Debug status information
- 4 LED patterns
- 5 Details about the interfaced serial, Ethernet or Fieldbus devices

North America (Corporate Location)	Europe / Middle East / Africa Regional Office
Phone: +1 661-716-5100	Phone: +33.(0)5.34.36.87.20
ps.prosofttechnology@belden.com	ps.europe@belden.com
Languages spoken: English, Spanish	Languages spoken: English, French, Hindi, Italian
REGIONAL TECH SUPPORT	REGIONAL TECH SUPPORT
ps.support@belden.com	ps.support.emea@belden.com
Latin America Regional Office	Asia Pacific Regional Office
Phone: +52.222.264.1814	Phone: +60.3.2247.1898
ps.latinam@belden.com	ps.asiapc@belden.com
Languages spoken: English, Spanish,	Languages spoken: Bahasa, Chinese, English,
Portuguese	Hindi, Japanese, Korean, Malay
REGIONAL TECH SUPPORT	REGIONAL TECH SUPPORT
ps.support.la@belden.com	ps.support.ap@belden.com

For additional ProSoft Technology contacts in your area, please see: www.prosoft-technology.com/About-Us/Contact-Us

2.2 Warranty Information

For details regarding ProSoft Technology's legal terms and conditions, please see: www.prosoft-technology.com/ProSoft-Technology-Legal-Terms-and-Conditions

For Return Material Authorization information, please see: www.prosoft-technology.com/RMA

ProSoft Technology, Inc. Page 6 of 6