

Date : 08.07.2011

Sierra Monitor Corporation
1991 Tarob Court
Milpitas CA 95035
USA

Attn: Michael C. Farr

Re. : CU US+Canada NRTL-Certificate

Type of Equipment : Slot Server
Model Designation : See Certificate
Certificate No. : CU 72103407 0002
File No. : 30581942 007
Engineer/Contact : Norman Chadwick
Standard(s) : UL 60950-1:2007
CAN/CSA-C22.2 No.60950-1-07

Dear Sir or Madame,

Enclosed you will find the additional page of certificate
No. CU 72103407 which incorporates your requested changes.

Please keep this page with your original certificate.

Call the TUV hotline at 1-TUV-Rheinland (1-888-743-4652)
to get answers for all your compliance needs.

If we can be of any further assistance to you, please do not
hesitate to contact us.

Sincerely yours,
Certification Body

for *MSOalc:*
Dipl.-Ing. M. Glagla
QA Certification Officer

Enclosure

TUV Rheinland
of North America, Inc.
North American Headquarters

12 Commerce Road
Newtown, CT 06470

Tel 203-426-0888
Fax 203-426-4009
Toll Free TUV-RHEINLAND
Mail info@tuv.com
Web www.tuv.com

Member of
TUV Rheinland Group

Certificate



Certificate no.

CU 72103407 02

License Holder:

Sierra Monitor Corporation
1991 Tarob Court
Milpitas CA 95035
USA

Manufacturing Plant:

Sierra Monitor Corporation
1991 Tarob Court
Milpitas CA 95035
USA

Test report no.: USA-NLC 30581942 007

Client Reference: Michael C. Farr

Tested to: UL 60950-1:2007
CAN/CSA-C22.2 No.60950-1-07

Certified Product: Slot Server


License Fee - Units

Addition:

Model Designation:

FieldServer Technologies PS56-AAA-xxx
(A = A-Z; x = 0-9, blank; not safety-relevant)

Licensed Test mark:



Signature

Date of Issue

(day/mo/yr)

07/07/2011

A handwritten signature in black ink, appearing to read "Martin Glagla".

Dipl.-Ing. M. Glagla
QA Certification Officer